

10/517,139
AIA 1/14/09

Application/Control Number: 10/517,139
Art Unit: 3747

Page 2

EXAMINER'S AMENDMENT

1. An examiner's amendment to the record appears below. Should the changes and/or additions be unacceptable to applicant, an amendment may be filed as provided by 37 CFR 1.312. To ensure consideration of such an amendment, it MUST be submitted no later than the payment of the issue fee.

Authorization for this examiner's amendment was given in a telephone interview with Kamran Emdadi (Reg. No. 58,823) on December 24, 2008.

AIA 1/14/09
In the specification, page 83, lines ~~1-3~~ must be read --fuel control appears to be that the sensitivity of the output V_{out} of the O_2 sensor 8 to the air-fuel ratio at the inflection point Y is neither excessively high nor small, but is appropriate--.

Conclusion

2. Any inquiry concerning this communication or earlier communications from the examiner should be directed to Johnny H. Hoang whose telephone number is (571) 272-4843.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Stephen K. Cronin can be reached on (571) 272-4536. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

EX.A
1/9/09